

EUROPEAN PATENT OFFICE  
U.S. PATENT AND TRADEMARK OFFICE

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

**The following classification changes will be effected by this Notice of Changes:**

<u>Action</u>	<u>Subclass</u>	<u>Group(s)</u>
<b>SCHEME:</b>		
Warnings Deleted:	B23Q	3/15526
	B23Q	2003/15527
	B23Q	2003/15528
	B23Q	2003/1553
	B23Q	2003/15531
	B23Q	2003/15532
	B23Q	3/15534
	B23Q	3/15536
	B23Q	2003/15537
	B23Q	3/15539
	B23Q	3/1554
	B23Q	2003/155404
	B23Q	2003/155407
	B23Q	2003/155411
	B23Q	2003/155414
	B23Q	2003/155418
	B23Q	2003/155421
	B23Q	2003/155425
	B23Q	2003/155428
	B23Q	2003/155432
	B23Q	2003/155435
	B23Q	2003/155439
	B23Q	2003/155442
	B23Q	2003/155446
	B23Q	2003/155449
	B23Q	2003/155453
	B23Q	2003/155456
	B23Q	3/1572
	B23Q	3/15722
	B23Q	3/15724

**No other subclasses/groups are impacted by this Notice of Changes.**

**This Notice of Changes includes the following [Check the ones included]:**

1. CLASSIFICATION SCHEME CHANGES

- A. New, Modified or Deleted Group(s)
- B. New, Modified or Deleted Warning(s)

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

- C. New, Modified or Deleted Note(s)
- D. New, Modified or Deleted Guidance Heading(s)

2. DEFINITIONS

- A. New or Modified Definitions (Full definition template)
  - B. Modified or Deleted Definitions (Definitions Quick Fix)
3.  REVISION CONCORDANCE LIST (RCL)
  4.  CHANGES TO THE CPC-TO-IPC CONCORDANCE LIST (CICL)
  5.  CHANGES TO THE CROSS-REFERENCE LIST (CRL)

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

1. CLASSIFICATION SCHEME CHANGES

B. New, Modified or Deleted Warning notice(s)

**SUBCLASS B23Q - DETAILS, COMPONENTS, OR ACCESSORIES FOR MACHINE TOOLS, e.g. ARRANGEMENTS FOR COPYING OR CONTROLLING (tools of the kind used in lathes or boring machines B23B27/00); MACHINE TOOLS IN GENERAL CHARACTERISED BY THE CONSTRUCTION OF PARTICULAR DETAILS OR COMPONENTS; COMBINATIONS OR ASSOCIATIONS OF METAL-WORKING MACHINES, NOT DIRECTED TO A PARTICULAR RESULT**

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
D	B23Q 3/15526	Group B23Q 3/15526 is impacted by reclassification into groups B23Q 2003/15527, B23Q 2003/15528, B23Q 2003/1553, B23Q 2003/15531, B23Q 2003/15532, B23Q 3/15534, B23Q 3/15536, B23Q 2003/15537 and B23Q 3/15539. All groups listed in this Warning should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/15527	Group B23Q 2003/15527 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/15527 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/15528	Group B23Q 2003/15528 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/15528 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/1553	Group B23Q 2003/1553 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/1553 should be considered in order to perform a complete search.	Delete the Warning.

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
D	B23Q 2003/15531	Group B23Q 2003/15531 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/15531 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/15532	Group B23Q 2003/15532 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/15532 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/15534	Group B23Q 3/15534 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 3/15534 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/15536	Group B23Q 3/15536 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 3/15536 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/15537	Group B23Q 2003/15537 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 2003/15537 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/15539	Group B23Q 3/15539 is incomplete pending reclassification of documents from group B23Q 3/15526. Groups B23Q 3/15526 and B23Q 3/15539 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/1554	Group B23Q 3/1554 is impacted by reclassification into groups B23Q	Delete the Warning.

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
		2003/155404, B23Q 2003/155407, B23Q 2003/155411, B23Q 2003/155414, B23Q 2003/155418, B23Q 2003/155421, B23Q 2003/155425, B23Q 2003/155428, B23Q 2003/155432, B23Q 2003/155435, B23Q 2003/155439, B23Q 2003/155442, B23Q 2003/155446, B23Q 2003/155449, B23Q 2003/155453 and B23Q 2003/155456. All groups listed in this Warning should be considered in order to perform a complete search.	
D	B23Q 2003/155404	Group B23Q 2003/155404 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155404 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155407	Group B23Q 2003/155407 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155407 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155411	Group B23Q 2003/155411 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155411 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155414	Group B23Q 2003/155414 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155414 should be considered in order to perform a complete search.	Delete the Warning.

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
D	B23Q 2003/155418	Group B23Q 2003/155418 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155418 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155421	Group B23Q 2003/155421 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155421 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155425	Group B23Q 2003/155425 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155425 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155428	Group B23Q 2003/155428 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155428 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155432	Group B23Q 2003/155432 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155432 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155435	Group B23Q 2003/155435 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155435 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155439	Group B23Q 2003/155439 is incomplete pending reclassification of documents	Delete the Warning.

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
		from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155439 should be considered in order to perform a complete search.	
D	B23Q 2003/155442	Group B23Q 2003/155442 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155442 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155446	Group B23Q 2003/155446 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155446 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155449	Group B23Q 2003/155449 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155449 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155453	Group B23Q 2003/155453 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155453 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 2003/155456	Group B23Q 2003/155456 is incomplete pending reclassification of documents from group B23Q 3/1554. Groups B23Q 3/1554 and B23Q 2003/155456 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/1572	Group B23Q 3/1572 is impacted by reclassification into groups B23Q 3/15722 and B23Q 3/15724. All groups listed in this Warning should	Delete the Warning.

CPC NOTICE OF CHANGES 1090

DATE: AUGUST 1, 2021

PROJECT RP0200-F

<u>Type*</u>	<u>Location</u>	<u>Old Warning notice</u>	<u>New/Modified Warning notice</u>
		be considered in order to perform a complete search.	
D	B23Q 3/15722	Group B23Q 3/15722 is incomplete pending reclassification of documents from group B23Q 3/1572. Groups B23Q 3/1572 and B23Q 3/15722 should be considered in order to perform a complete search.	Delete the Warning.
D	B23Q 3/15724	Group B23Q 3/15724 is incomplete pending reclassification of documents from group B23Q 3/1572. Groups B23Q 3/1572 and B23Q 3/15724 should be considered in order to perform a complete search.	Delete the Warning.

\*N = new warning, M = modified warning, D = deleted warning

NOTE: The "Location" column only requires the symbol PRIOR to the location of the warning. No further directions such as "before" or "after" are required.