

EUROPEAN PATENT OFFICE
U.S. PATENT AND TRADEMARK OFFICE

CPC NOTICE OF CHANGES 1530

DATE: JANUARY 1, 2024

PROJECT RP0733-F

The following classification changes will be effected by this Notice of Changes:

<u>Action</u>	<u>Subclass</u>	<u>Group(s)</u>
SCHEME:		
Warnings Deleted:	H02K	1/278, 1/2781, 1/2783, 1/2786, 1/2787, 1/2793, 1/2795

No other subclasses/groups are impacted by this Notice of Changes.

This Notice of Changes includes the following *[Check the ones included]:*

1. CLASSIFICATION SCHEME CHANGES

- A. New, Modified or Deleted Group(s)
- B. New, Modified or Deleted Warning(s)
- C. New, Modified or Deleted Note(s)
- D. New, Modified or Deleted Guidance Heading(s)

2. DEFINITIONS

- A. New or Modified Definitions (Full definition template)
- B. Modified or Deleted Definitions (Definitions Quick Fix)

3. REVISION CONCORDANCE LIST (RCL)

4. CHANGES TO THE CPC-TO-IPC CONCORDANCE LIST (CICL)

5. CHANGES TO THE CROSS-REFERENCE LIST (CRL)

CPC NOTICE OF CHANGES 1530

DATE: JANUARY 1, 2024

PROJECT RP0733-F

1. CLASSIFICATION SCHEME CHANGES

B. New, Modified or Deleted Warning(s)

SUBCLASS H02K – DYNAMO-ELECTRIC MACHINES

<u>Type*</u>	<u>Location</u>	<u>Old Warning</u>	<u>New/Modified Warning</u>
D	H02K 1/278	Group H02K 1/278 is impacted by reclassification into groups H02K 1/278 1 and H02K 1/2783. Groups H02K 1/278, H02K 1/278 1 and H02K 1/2783 should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2781	Group H02K 1/2781 is incomplete pending reclassification of documents from group H02K 1/278. Groups H02K 1/278 and H02K 1/2781 should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2783	Group H02K 1/2783 is incomplete pending reclassification of documents from group H02K 1/278. Groups H02K 1/278 and H02K 1/2783 should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2786	Group H02K 1/2786 is impacted by reclassification into groups H02K 1/2787, H02K 1/2788, H02K 1/2789, H02K 1/279, H02K 1/2791, H02K 1/27915 and H02K 1/2792. All groups listed in this Warning should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2787	Groups H02K 1/2787, H02K 1/2788, H02K 1/2789, H02K 1/279, H02K 1/2791, H02K 1/27915 and H02K 1/2792 are incomplete pending reclassification of documents from group H02K 1/2786. All groups listed in this Warning should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2793	Group H02K 1/2793 is impacted by reclassification into groups H02K 1/2795, H02K 1/2796 and H02K 1/2798. All groups listed in this Warning should be considered in order to perform a complete search.	DELETE the entire Warning
D	H02K 1/2795	Groups H02K 1/2795, H02K 1/2796 and H02K 1/2798 are incomplete pending reclassification of documents from group H02K 1/2793. All groups listed in this Warning should be considered in order to perform a complete search.	DELETE the entire Warning

CPC NOTICE OF CHANGES 1530

DATE: JANUARY 1, 2024

PROJECT RP0733-F

*N = new warning, M = modified warning, D = deleted warning

NOTE: The "Location" column only requires the symbol PRIOR to the location of the warning. No further directions such as "before" or "after" are required.