EUROPEAN PATENT OFFICE U.S. PATENT AND TRADEMARK OFFICE

CPC NOTICE OF CHANGES 1743

DATE: MAY 1, 2025

PROJECT RP11761-F

The following classification changes will be effected by this Notice of Changes:

Action	<u>Subclass</u>	Group(s)	
Warming Delete I	TITON	10/055 10/055/	
Warnings Deleted:	H10N	10/855, 10/8556	
	H10N	19/00	
	H10N	30/00, 30/80, 30/85	
	H10N	35/00,35/80,35/85	
	H10N	39/00	
	H10N	50/00, 50/20, 50/85	
	H10N	52/85	
	H10N	59/00	
	H10N	69/00	
	H10N	79/00	
	H10N	89/00	

No other subclasses/groups are impacted by this Notice of Changes.

This Notice of Changes includes the following [Check the ones included]:

1. CL	ASSIF	FICATION SCHEME CHANGES
		A. New, Modified or Deleted Group(s)
	\boxtimes	B. New, Modified or Deleted Warning(s)
		C. New, Modified or Deleted Note(s)
		D. New, Modified or Deleted Guidance Heading(s)
2. DE	FINIT	TONS
		A. New or Modified Definitions (Full definition template)
		B. Modified or Deleted Definitions (Definitions Quick Fix)
3. 🗌	REV	TSION CONCORDANCE LIST (RCL)
4. 🗌	CHA	ANGES TO THE CPC-TO-IPC CONCORDANCE LIST (CICL)
5. 🗆	CHA	ANGES TO THE CROSS-REFERENCE LIST (CRL)

DATE: MAY 1, 2025

PROJECT RP11761-F

1. CLASSIFICATION SCHEME CHANGES

B. New, Modified or Deleted Warning notice(s)

SUBCLASS H10N-ELECTRIC SOLID-STATE DEVICES NOT OTHERWISE PROVIDED FOR

Type*	<u>Location</u>	Old Warning notice	New/Modified Warning
D	H10N10/855	Group H10N 10/855 is impacted by reclassification into group H10N 10/8556. Groups H10N 10/8556 and H10N 10/8556 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N10/8556	Group H10N 10/8556 is incomplete pending reclassification of documents from group H10N 10/855. Groups H10N 10/855 and H10N 10/8556 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N19/00	Group H10N 19/00 is incomplete pending reclassification of documents from groups H01L 25/16, H01L 25/162, H01L 25/167 and H01L 25/18. All groups listed in this Warning should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N30/00	Group H10N 30/00 is impacted by reclassification into group H10N 35/00. Groups H10N 30/00 and H10N 35/00 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N30/80	Group H10N 30/80 is impacted by reclassification into group H10N 35/80. Groups H10N 30/80 and H10N 35/80 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.

DATE: MAY 1, 2025

PROJECT RP11761-F

_			
D	H10N30/85	Group H10N 30/85 is impacted by reclassification	<u>Delete</u> the entire Warning.
		into group H10N 35/85.	
		Groups H10N 30/85 and	
		H10N35/85 should be	
		considered in order to	
		perform a complete search.	
D	H10N35/00	Group H10N 35/00 is	<u>Delete</u> the entire Warning.
		incomplete pending	
		reclassification of documents	
		from group H10N 30/00.	
		Groups H10N 30/00 and	
		H10N35/00 should be	
		considered in order to	
		perform a complete search.	
D	H10N35/80	Group H10N 35/80 is	Delete the entire Warning.
		incomplete pending	_
		reclassification of documents	
		from group H10N 30/80.	
		Groups H10N 30/80 and	
		H10N35/80 should be	
		considered in order to	
		perform a complete search.	
D	H10N35/85	Group H10N 35/85 is	<u>Delete</u> the entire Warning.
		incomplete pending	
		reclassification of documents	
		from group H10N 30/85.	
		Groups H10N 30/85 and	
		H10N 35/85 should be	
		considered in order to	
		perform a complete search.	
D	H10N39/00	Group H10N 39/00 is	Delete the entire Warning.
		incomplete pending	
		reclassification of documents	
		from groups H01L 25/16,	
		H01L 25/162, H01L 25/165,	
		H01L25/167 and H01L	
		25/18. All groups listed in	
		this Warning should be	
		considered in order to	
		perform a complete search.	
D	H10N50/00	Group H10N 50/00 is	Delete the entire Warning.
		impacted by reclassification	
		into group H10N 50/20.	
		Groups H10N 50/00 and	
		H10N 50/20 should be	
		considered in order to	
		perform a complete search.	
		perform a complete scarcil.	

DATE: MAY 1, 2025

PROJECT RP11761-F

D	H10N50/20	Group H10N 50/20 is incomplete pending reclassification of documents from group H10N 50/00. Groups H10N 50/00 and H10N 50/20 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N50/85	Group H10N 50/85 is impacted by reclassification into group H10N 52/85. Groups H10N 50/85 and H10N 52/85 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N 52/85	Group H10N 52/85 is incomplete pending reclassification of documents from group H10N 50/85. Groups H10N 50/85 and H10N 52/85 should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.
D	H10N 59/00	Group H10N 59/00 is incomplete pending reclassification of documents from groups H01L 25/16, H01L 25/162, H01L 25/167, and H01L 25/18. Group H10N 59/00 is also impacted by reclassification into group H10B 61/00. All groups listed in this Warning should be considered in order to perform a complete search.	Delete the entire Warning.
D	H10N69/00	Group H10N 69/00 is incomplete pending reclassification of documents from groups H01L 25/16, H01L 25/162, H01L 25/167, and H01L 25/18. All groups listed in this Warning should be considered in order to perform a complete search.	<u>Delete</u> the entire Warning.

DATE: MAY 1, 2025

PROJECT RP11761-F

D	H10N79/00	Group H10N 79/00 is	Delete the entire Warning.
		incomplete pending	
		reclassification of documents	
		from groups H01L 25/16,	
		H01L 25/162, H01L 25/165,	
		H01L 25/167, H01L 25/18,	
		and H10B63/00. All groups	
		listed in this Warning should	
		be considered in order to	
		perform a complete search.	
D	H10N89/00	Group H10N 89/00 is	Delete the entire Warning.
		incomplete pending	
		reclassification of documents	
		from manna H011 25/16	
		from groups H01L 25/16,	
		H01L25/162, H01L25/165,	
		H01L25/162, H01L25/165, H01L25/167 and H01L	
		H01L 25/162, H01L 25/165, H01L 25/167 and H01L 25/18. All groups listed in	
		H01L 25/162, H01L 25/165, H01L 25/167 and H01L 25/18. All groups listed in this Warning should be	
		H01L 25/162, H01L 25/165, H01L 25/167 and H01L 25/18. All groups listed in	

N = new warning, M = modified warning, D = deleted warning

NOTE: The "Location" column only requires the symbol PRIOR to the location of the warning. No further directions such as "before" or "after" are required.